


Stair LED Aluminum Profile-S003





With Lighting Symbol



Step 1 drilled the hole on the step profile *5PCS



Step 2 row number *1 Screws spec: M3*16 *2PCS



Step 3 Put the cable of the row number through the hole



Step 4



Step 8 Power supply



Step 7 led strip + connect to row number +, led strip- connect to row number -(black-,red +)



Step 6 fixed the row number by M3*16 screw on the profile



Step 5 Screw the Lighting symbol on the lamp slot



Step 9 LED light connect to power supply (black-,red +)

